

DATE 10-22-59
SH. 1 OF 1
COMPILED BY

TMC SPECIFICATION NO. S-463

TITLE: CONVERSION OF MSR-4 to MSR-3a

JOB

APPROVED



- TB-1 - C26 Change
CC-100-9 to CC-100-16

- TB-2 - C35 Change
CC-100-16 to CC-100-28

- R37 Change
RC20GF223K to RC20GF334K

- TB-4 - R44 Change
RC20GF474K to RC20GF684K

- R45 Change
RC20GF474K to RC20GF154K

Relay K2 replace C31

CM20E510J to C1-130-6.4 uh coil
Rewire to lower lug K2 (Check Schematic)
Delete symbol C31 restamp L3

Add R70 (RC20GF223K)

Wire from S4 pin 1 to Z3, black dot (ground)

Replace Z3

A-1387 to A-1507

Replace Crystal Y1

CR46/U-.4380P to CR-105-1-.1830P

Replace Crystal Y2

CR46/U-.4720P to CR-105-1-.2170P