

| REQ | ITEM | PART NUMBER | BREAKOUT | | DESTINATION OR DESCRIPTION | |
|-----|------|----------------|----------|----|----------------------------|---------|
| | | | FROM | TO | FROM | TO |
| | 26 | LWC22(7)U92 | 4 | 7 | S10-10 | J1-V |
| | 27 | 92 | 6 | 7 | S12-10 | J1-h |
| | 28 | 93 | 2 | 7 | S8-9 | J1-J |
| | 29 | 93 | 4 | 7 | S10-9 | J1-W |
| | 30 | 93 | 6 | 7 | S12-9 | J1-j |
| | 31 | 94 | 2 | 7 | S8-8 | J1-K |
| | 32 | 94 | 4 | 7 | S10-8 | J1-X |
| | 33 | 94 | 6 | 7 | S12-8 | J1-k |
| | 34 | 95 | 2 | 2 | S2-3 | S8-W |
| | 35 | 95 | 2 | 7 | S8-W | J1-L |
| | 36 | 95 | 4 | 4 | S4-3 | S10-W |
| | 37 | 95 | 4 | 7 | S10W | J1-Y |
| | 38 | 95 | 6 | 6 | S6-3 | S12-W |
| | 39 | 95 | 6 | 7 | S12-W | J1-l |
| | 40 | 96 | 2 | 7 | XDS2 | J1-M |
| | 41 | 96 | 4 | 7 | XDS-4 | J1-z |
| | 42 | 96 | 6 | 7 | XDS6 | J1-m |
| | 43 | 0 | 7 | 7 | J1-5 | GND |
| | 44 | LWC22(7)U0 | 7 | 7 | J1-6 | GND |
| 1 | 45 | MS3102A32-414P | | | CONN, RECP, ML | 52/C J1 |
| | 46 | PX100-1-106 | | | INS, SLUG, BLK | |
| 1 | 47 | TE104-2 | | | TERM, LUG | |
| 24 | 48 | CU142-6 | | | STRAP, CBC | |
| | 49 | CD101-1MW | | | CORP, NY LON, LACING | |
| 50 | 50 | BS160 | | | SOLDER, TIN ALLOY | |