

SWR INDICATOR

MODEL SWR-3K-50

REV

TITLE

USED ON

MODEL SECTION
SWR-3K-70

LIST SECTIONS

- 1.SUPPORTING NOTES
- 2.SUPPORTING LISTS
- 3.ELECTRICAL/MECHANICAL
- 4.SUPP ASSY/REF DWGS
- 5.SPECIFICATIONS
- 6.LOOSE ITEMS
- 7.PARTS PECULIAR

SHEET NO.

- SEE BELOW
- 1
- 2
- 3
- NONE
- 4
- NONE

LAST SYMBOLS

NONE

COMPILED L. GABEL
 CHECKED L. GABEL
 APPROVED F. BUDETTI
 FNL APPR *L. Gabel*
 ISS DATE 12-31-64

MISSING SYMBOLS

NONE

NOTE 2.CA988 AND ITS ASSOCIATED PARTS SHALL BE SHIPPED ONLY UPON CUSTOMERS REQUEST.SEE NOTE 4.

NOTE 3.ALL ITEMS REFERENCED TO THIS NOTE SHALL BE SHIPPED AS LOOSE ITEMS WHEN CA988 IS NOT REQUESTED BY CUSTOMER.SEE NOTE 4.

NOTE 1.THE FOLLOWING SYMBOL,#,IN THE REMARKS COLUMN INDICATES THAT THE PART NUMBER IMMEDIATELY FOLLOWING IT IS THE TMC PROPRIETARY MANUFACTURING DRAWING FOR THE CORRESPONDING NUMBER IN THE PART NUMBER COLUMN.

NOTE 4.ALL LOOSE ITEMS WILL BE OMITTED WHEN THIS UNIT IS SHIPPED AS PART OF A SYSTEM.

NOTE 5.OPTIONAL EQUIPMENT AVAILABLE FOR USE WITH THIS SYSTEM.

- JB111 JUNCTION BOX
- SWR-3K-PM PORTABLE METER
- CAB-1 CABINET

**MATERIAL LIST /
NUMERICAL PARTS LIST**

REV.

MODEL:

SWR-3K-50

SHEET 1 OF 4

PART NO.	DESCRIPTION SUPPORTING LISTS	ITEM LOCATION			QTY. PER UNIT	REFERENCE SYMBOLS	REMARKS
		USED ON ASSEMBLY	USED TO MOUNT	QTY. PER USED TO MOUNT			
CU-3K-50	DIR COUPLER	SWR-3K-50			1		
SWR-3K-RM	IND-CONTROL	SWR-3K-50			1		

**MATERIAL LIST /
NUMERICAL PARTS LIST**

REV.

MODEL:

SWR-3K-50

SHEET 2

OF 4

PART NO.	DESCRIPTION ELECTRICAL/MECHANICAL	ITEM LOCATION			QTY. PER UNIT	REFERENCE SYMBOLS	REMARKS
		USED ON ASSEMBLY	USED TO MOUNT	QTY. PER USED TO MOUNT			
BS100	SOLDER, TIN ALY	CA988-XX					NOTE 2
MS3057-6	CLP, CBL, EL CONN	CA988-XX			2		NOTE 2
MS3106A14S2P	CONN, PL, ML	CA988-XX			1		NOTE 2
MS3106A14S2S	CONN, PL, FML	CA988-XX			1		NOTE 2
MS3420-6A	BUSH. , RUB.	CA988-XX			2		NOTE 2
WI130-3-20-XX	CBL, SP	CA988-XX			1		NOTE 2
WL100-7	WIRE ,ELEC, BUSS	CA988-XX			1		NOTE 2

**MATERIAL LIST /
NUMERICAL PARTS LIST**

REV.

MODEL:

SWR-3K-50

SHEET 3 OF 4

PART NO.	DESCRIPTION SUPP ASSY/REF DWGS	ITEM LOCATION			QTY. PER UNIT	REFERENCE SYMBOLS	REMARKS
		USED ON ASSEMBLY	USED TO MOUNT	QTY. PER USED TO MOUNT			
CK891	DIAG,WRG	SWR-3K-50			1		

**MATERIAL LIST /
NUMERICAL PARTS LIST**

REV.

MODEL:

SWR-3K-50

SHEET 4

OF 4

PART NO.	DESCRIPTION LOOSE ITEMS	ITEM LOCATION			QTY. PER UNIT	REFERENCE SYMBOLS	REMARKS
		USED ON ASSEMBLY	USED TO MOUNT	QTY. PER USED TO MOUNT			
CA988-XX	CBL ASSY,SP	SWR-3K-50					NOTE 2
MS3057-6	CLP,CBL,EL CONN	SWR-3K-50			2		NOTE 3
MS3106A14S2P	CONN,PL,ML	SWR-3K-50			1		NOTE 3
MS3106A14S2S	CONN,PL,FML	SWR-3K-50			1		NOTE 3
MS3420-6A	BUSH.,RUB.	SWR-3K-50			2		NOTE 3