



# MATERIAL LIST

A-4625  
REV. Ø

PAGE 1 OF

PART NUMBER	DESCRIPTION	USED ON	QUANTITY	QUANTITY PER UNIT	REFERENCE SYMBOLS	SPECIAL NOTES REFER TO S 1200
CC100-29	CAP., FXD, CER	A-4625	1		C1	
		A-4625	1		C2	
		A-4625	1		C3	
		A-4625	1	4*	C4	
CK1611	DIAG, SCHEM	A-4625	1	1*		
NW142-24	NW DIG AND/GATE	A-4625	1		Z4	
		A-4625	1	2*	Z5	
NW142-34	NW DIG AND/GATE	A-4625	1	1*	Z7	
NW150-4	NW DIG INVERT	A-4625	1		Z8	
		A-4625	1	2*	Z9	
NW151	NW DIG F/F	A-4625	1		Z1	
		A-4625	1		Z2	
		A-4625	1		Z3	
		A-4625	1	4*	Z6	
PC396	PC BD	A-4625	1	1*		
TE0127-2	TERM., STUD	PC396	1		TP1	
		PC396	1		TP2	
		PC396	1		TP3	
		PC396	1		TP4	
		PC396	1		TP5	
		PC396	1		TP6	
		PC396	1		TP7	
		PC396	1		TP8	
		PC396	1		TP9	
		PC396	1		TP10	
		PC396	1		TP11	
		PC396	1		TP12	
		PC396	1		TP13	
		PC396	1		TP14	
		PC396	1		TP15	

# MATERIAL LIST

A-4625  
REV. Ø

PAGE 2 OF

PART NUMBER	DESCRIPTION	USED ON	QUANTITY	QUANTITY PER UNIT	REFERENCE SYMBOLS	SPECIAL NOTES REFER TO S 1200
		PC396 PC396 PC396 PC396 PC396	1 1 1 1 1	20*	TP16 TP17 TP18 TP19 TP20	