

PRELIMINARY

MATERIAL LIST

FINAL

FOR

REVISION

TOTAL SHEETS 2

TMC MODEL - A5611

TITLE - D.C. COUPLER

REV.	SHEET (S)	DATE	APPR.
		1/9/75	
		2/3/75	
0			

USED ON
MODEL - TMA-1K

CONSISTS OF
SUPPORTING LISTS

LAST SYMBOLS SYMBOLS NOT USED

COMPILED _____
CHECKED _____
ENG APPR _____
FNL APPR _____
ISS DATE _____

ENGINEERING JOB NUMBER
E _____

§ FOR SPECIAL NOTES,
REFER TO S1200.

MATERIAL LIST

A5611
REV. Q

PAGE 1 OF 2

PART NUMBER	DESCRIPTION	USED ON	QTY.	QTY. PER UNIT	REFERENCE SYMBOLS	SPECIAL NOTES REFER TO S1200
A5612	ASSY, PISTON CAP	A5611	1	1*	C1	P.O.
CC100-43	CAP, FXD, COMP.	A5611	1	1*	C3	
CI128-1	CORE, TOROID	TZ235	1	1*	T1	P.O.
CK2085	DIAGRAM, SCHEMATIC	A5611	1	1*		
CL275	COIL, RF	A5611	1	1*	L1	
CM111F221J1S	CAP, FXD, COMP.	A5611	1	1*	C2	
MS6570	PLT, OUTPUT MTG.	A5611	1	1*		
MS6571	COVER (TOP)	A5611	1	1*		
MS6572	COVER (BOTTOM)	A5611	1	1*		
MS6574-1	PLT, CAP.	A5611	1		C1	P.O.
		A5612	1	2*	C1	P.O.
MS6574-2	PLT, COIL	A5611	1	1*		
MS6575	FEED THROUGH	A5611	1	1*		
NS03W104	INS, STANDOFF	A5611	1	1*		
PX1249	LINE INSULATOR	A5611	2	2*		
PX1250	CAP, INSULATOR	A5611	1	1*		
RC07GF100J	RES, FXD, COMP.	A5611	1	1*	R1	
SC143-1032B20	SCREW, NYLON	A5611	1	1*		
SCPF0632BN14	SCREW, FLT. H.D.	A5612	1	1*		

MATERIAL LIST

A5611
REV. 0

PAGE 2 OF 2

PART NUMBER	DESCRIPTION	USED ON	QTY.	QTY. PER UNIT	REFERENCE SYMBOLS	SPECIAL NOTES REFER TO S1200
SP147	SPRING, HELICAL	A5611	1	1*		
TE104-1	TERM, LOCKING	A5611	1	1*		
TE110-1	LUG, SOLDER	A5611	1	1*		
TE110-4	LUG, SOLDER	A5611	2	2*		
TE115-1	TERM, TURRET	A5611	2	2*		
TE193B4S9	TERM, FEED THROUGH	A5611	1	1*		
TZ235	TRANS, RF	A5611	1	1*	T1	
WA101-4	WASHER, FLAT	A5611	1	1*		
WA101-6	WASHER, FLAT	A5611	1	1*		
WA101-7	WASHER, FLAT	A5611	1	1*		
WI-141-32-2	WIRE	TZ235	1	1*		
1N100	SCOND, DEV, DIO	A5611	1	1*	CR1	

TOTAL SHEETS-

REVISIONS

USED ON
MODEL-

TMAC-1K

REV.	SHEET(S)	DATE	APPR.
0	Original Re	2/10/78	

FOR

MODEL A5611

TITLE DC COUPLER

LAST SYMBOLS

- C3
- L1
- R1

CONSISTS OF
SUPPORTING LISTS

COMPILED W. J. Burns

CHECKED _____

KEY PUNCHED _____

MISSING SYMBOLS

ENGINEERING JOB ORDER

E _____

§ FOR SPECIAL NOTES,
REFER TO S1200.

**MATERIAL LIST /
NUMERICAL PARTS LIST**

REV. \emptyset

MODEL: A5611

SHEET 1 OF 2

PART NO.	DESCRIPTION	ITEM LOCATION			QTY. PER UNIT	REFERENCE SYMBOLS	REMARKS
		USED ON ASSEMBLY	USED TO MOUNT	QTY. PER USED TO MOUNT			
A5612	ASSY, PISTON CAP.	A5611		1	1	C1	
CC100-43	CAP, FXD, CER.	A5611		1	1	C3	
CL275-471	COIL, FXD, RF	A5611		1	1	L1	
CM111F221J5S	CAP. FXD, MICA	A5611		1	1	C2	
MS6574-1	PLATE, CAP	A5611		1	1		
MS6574-2	PLATE, COIL & CAP	A5611		1	1		
MS6575	FEEDTHRU, OUTPUT CPLR	A5611		1	1		
MS6570	PALTE, OUTPUT MTG.	A5611		1	1		
PX 1249	INS, OUTPUT CPLR	A5611		2	2		
PX 1250	INS, CAP	A5611		2	2		
NS3W0104	INS, STNADOFF, RND	A5611		1	1		
SP147	SPG, HEL, COMP.	A5611		1	1		
RC07GF100J	RES, FXD, COMP.	A5611		1	1	R1	
TE104-1	TERM, LKG.	A5611		1	1		
TE110-1	LUG, SOLDER	A5611		1	1		
TE110-4	LUG, SOLDER	A5611		2	2		
TE115-1	TERM, TURRET	A5611		2	2		
TE193B4S9	TERM, FEEDTHRU	A5611		1	1		
TZ235	TRANSFORMER, R.F.	A5611		1	1	T1	

**MATERIAL LIST /
NUMERICAL PARTS LIST**

REV. 0

MODEL: A5611

SHEET 2 OF 2

PART NO.	DESCRIPTION	ITEM LOCATION			QTY. PER UNIT	REFERENCE SYMBOLS	REMARKS
		USED ON ASSEMBLY	USED TO MOUNT	QTY. PER USED TO MOUNT			
WA101-4	WASH., FIB, FL	A5611		2	2		
WA101-6	WASH., FIB, FL	A5611		1	1		
WA101-7	WASH., FIB. FL	A5611		1	1		
SC143-1032B18	SCR, MACH, NYLON	A5611		1	1		
1N100	SCOND, DEV, DIO	A5611		1	1	CR1	
CK2085	SCHEMATIC DIAGRAM	A5611		1			