

USED ON

MODEL	SECTION	QUAN.
GPR-90	1	1
RTC	1	1

CAB-2	
LIST NO.	REV.

CABINET, ELECT. EQUIPMENT
(TITLE)

LIST SECTIONS

- 1. ELECTRICAL / MECHANICAL (PG.1)
- 2. HARDWARE (PG.2)
- 3. RAW MATERIALS NONE REQ.
- 4. SUPPORTING DRAWINGS (PG.3)
- 5. SPECIFICATIONS NONE REQ.
- 6. LOOSE ITEMS (PG.4)
- 7. PARTS PECULIAR NONE REQ.

TYPED 2/8/62

CHECKED VB

APPROVED VB BR

MATERIAL LIST

REV

MODEL CAB-2

SHEET 1 OF 4

QUAN. PER UNIT	PART NO.	DWG. REV.	DWG. SIZE	DESCRIPTION ELECTRICAL/MECHANICAL	REF.	LOCATION		SYMBOLS
						USED ON	QUAN.	
1	A-1228			Cabinet, Elect. Equipment		A-2283		
1	GA-138-2			Gasket		A-1228		
4	PX-277			Case Mount		A-2283		

MATERIAL LIST

REV

MODEL CAB-2

SHEET 2 OF 4

QUAN. PER UNIT	PART NO.	DWG. REV.	DWG. SIZE	DESCRIPTION HARDWARE	REF.	LOCATION		SYMBOLS
						USED ON	QUAN.	
4	FW10HBN			Washer, Flat		A-2283	4	
4	LWE10MRN			Washer, Lock		A-2283	4	
4	NTH1032BN10			Nut, Hexagon		A-2283	4	
4	SCBP1032BN20			Screw, Machine		A-2283	4	

MATERIAL LIST

REV

MODEL CAB-2

SHEET 3 OF 4

QUAN. PER UNIT	PART NO.	DWG. REV.	DWG. SIZE	DESCRIPTION SUPPORTING DRAWINGS	REF.	LOCATION		SYMBOLS
						USED ON	QUAN.	
1	A-2283			Final Assembly, CAB-2				
1	CAB-2			Cabinet, Elect. Equipment 20-3/8 x 15 x 10-1/8				

MATERIAL LIST

REV

MODEL CAB-2
SHEET 4 OF 4

QUAN. PER UNIT	PART NO.	DWG. REV.	DWG. SIZE	DESCRIPTION LOOSE ITEMS	REF.	LOCATION		SYMBOLS
						USED ON	QUAN.	
4	SCBP1032BN8			Screw, Machine		A-2283	4	
4	WA-101-51			Washer, Fibre		A-2283	4	