USED ON				R390				
MODEL	SECTION			LIST NO.	REV.			
DDR-9A								
		TMC MODIFICATIONS TO RECEIVER (COLLINS R390)						
			(TITLE)					
			LIST SECTIONS					
		LAST SYMBOLS	1. SUPPORTING LISTS (None	Peg)				
		P101						
		₩101	2. ELECTRICAL / MECHANICA	(NONE REQ.)				
			3. TUBES/DIODES	(NONE REQ.)				
	8	Missing Symbols	4. HARDWARE					
		NONE	5. RAW MATERIALS	(NONE REQ.)				
			6. SUPPORTING DRAWINGS	(NONE REQ.)				
			7. SPECIFICATIONS	(NONE REQ.)				
			8. LOOSE ITEMS	((None Req.)				
			9. PARTS PECULIAR	(Pg. 1)				
			TYPED 6-/					
			CHECKED 166-1 AM 1/5/	67				
			APPROVED 66-1					
			FINAL APPR	1				
	AND REAL PROPERTY OF THE PARTY							

TMC FORM MLT-1, OGILVIE PRESS, INC. NO. 459M TYPEMASTER

M	ATERIAL LIST	REV.	MODEL R390				
	ATERIAL LIST			SHE	THE RESIDENCE IN COLUMN TWO IS NOT THE	OF	1
QUAN.	PART NO.	DESCRIPTION PARTS PECULIAR	REF.	USED ON	USED TO MOUNT	QUAN.	REF. SYMBOLS AND/OR REMARKS
1	CA-57 5- 2	When R390 is shipped with DDR-9A, TMC must replace existing AC cable with the following: Cable, AC Power, Coiled CONSISTS OF-	23.10			1	W101
1	PL-171	Conn, Plug, AC		CA-575		1	P101
2	TE-120-2	Terminal, Lug, Size 6		CA-575		2	
1-0	WI -134-2-12	Cable, AC, Coiled		CA-575		1-0	
THE	TECHNICAL MATERIE	COPPORATION				VA MA	ARONECK, NEW YORK